

मुख्य अग्निशमन अधिकारी
OFFICE OF THE CHIEF FIRE OFFICER
अण्डमान तथा निकोबार द्वीप समूह
Andaman and Nicobar Islands

Clearance Number : **FS/FCC/2026/1947**


, Port Blair dated **06/03/2026**

FIRE CLEARANCE CERTIFICATE

This is to certify that the **ST. XAVIER SCHOOL** situated at **ST. XAVIER SCHOOL, MANNARGHAT,P.O WIMBERLYGUNJ. FERRARGUNJ, SOUTH ANDAMAN, NEAR FOREST RANGE OFFICE, SURVEY NO: 179,181,184,181,178 PIN-744206 ,WIMBERLYGUNJ ,FERRARGUNJ** bearing Survey No. **179,181,184,181,178** has been inspected and there is "**NO OBJECTION**" from fire safety point of view.The First Aid Fire Fighting arrangements in the **School** are found satisfactory and realiable for a period of one (1) year from the date of issue of this FCC, subject to no change is effected in the existing fire fighting arrangements.

Note:- Conditions for the validity of Fire Clearance Certificate (FCC)

1. The school comprised of one RCC Block having two floors (Ground +1 floors) for functioning of classes from Nursery to XII standard.
2. The school building should not be used for any purpose after sunset.
3. Building stability and satisfactory electrical installation to be ascertained from concerned agency.
4. FCC may not be treated in any case for regularization of unauthorized construction, if any or violation in building plan.
5. FCC shall stand null and void if there is any violation in existing firefighting arrangements.
6. The FCC shall have no legal standing or authority concerning the ownership of the School.
7. FCC, may not be treated in any case for regularization of unauthorized construction, if any or violation in building plan.
8. All fire safety arrangements provided therein shall be maintained in good working conditions at all time and all staff members shall be well acquainted to operate all fire safety equipment.


ST. XAVIER SR. SEC. SCHOOL
Mannarghat, Wimberlygunj
South Andaman- 744 206

9. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
10. All staff should be trained in firefighting. Trained firefighting staff should be available round the clock.
11. Any deviation with regard to construction etc. shall be verified* by the concerned building sanctioning authority.
12. Means of escape shall be kept un-obstructed/unlocked for unhindered evacuation in case of an emergency.
13. Occupant load in class room should be calculated at not less than 4 m² per students.
14. Students of Classes from pre-primary to 1st Standard should be accommodated at ground floor only.
15. No combustible material should be used for construction of school building.
16. The firefighting equipment register, mock drill register and staff training register should be updated regularly.

Copy to:-

1. The Secretary, RD for kind information
2. The Director of Education for kind information



Inspector Fire Brigade (Port
Blair)
Andaman and Nicobar Islands

To

DEONIS KERKETTA
ST. XAVIER SCHOOL,
MANNARGHAT, P.O
WIMBERLYGUNJ.
FERRARGUNJ, SOUTH
ANDAMAN, NEAR
FOREST RANGE
OFFICE, SURVEY NO:
179,181,184,181,178
PIN-744206
WIMBERLYGUNJ
FERRARGUNJ